

1/4





FIG. 1
PRIOR ART

2/4



RLOAD=200 OHMS (60 mm X 100 mm) _____

RLOAD=200 OHMS (6 mm X 10 mm) - - - - -

FIG. 2
PRIOR ART

3/4




FIG. 3

4/4




FIG. 4